

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)**

Incident Date & Time 11/15/2015 07:40		Reported Date & Time 11/15/2015 08:43		Activity Type Spill		BRRTS No. 04-36-576431		SPILL ID 20151115NE36-1	
Reported to DATCP? No		Transferred to DATCP? No		NFA Letter Sent? Yes No		Transferred to ERP? No		Status Closed	
Location									
DNR Region NE		Mgmt Region NE		County Manitowoc		Municipality NEWTON, TOWNSHIP OF		Parcel No.	
Location Name ROW						Address CTY HWY F			
Location Description N SIDE OF THE RD, 1/4 MI W OF S UNION RD, SHOULDER/DITCH AREA									Facility ID
Location Type Roadway (Public Road/Highway/Street/Alley/ROW)						PLSS Description			
WTM 697524X 391942 Y			Latitude/Longitude 0 ' " 0 ' "						
Responsible Parties									

MAPLE LEAF DAIRY
6832 CTH X
CLEVELAND WI 53015

Cause	
Type Transportation Accident, Load Spill	
Other Cause	
Cause Description	

Substances						
Substance Manure [Manure]				Substance Other		
Quantity Released 750.00	Quantity Recovered	UOM Gallon	Physical Characteristic LIQUID	Color	Odor	

Environmental Impacts					
Impact to Soil Contamination		Other Desc		Surface Water Name	
Resource Damages? No	Resource Damage Type				
Resource Damage Comment					
Injuries? No	Injury Count 0	Injury Comment			
Evacuation? No	Evacuation Count 0	Evacuation Comment			

Response	
Enforcement Action? No	Enforcement Type
Enforcement Comment	

SPILL ID: 20151115NE36-1 BRRTS No: 04-36-576431

SPILL ID: 20151115NE36-1 BRRTS No: 04-36-576431

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report (SERTS)**

ERDMAN

Cleanup Actions

Flow Stopped

No Action Needed

Cleanup Comments

OCSC SPOKE WITH MAPLE LEAF DAIRY. THE TRUCK WAS TRAVELING AT 55 MPH HOUR WHEN THEY HIT THE SWITCH AND THE VALVE OPENED. NONE WAS ON THE ROAD, IT WAS ON THE SHOULDER. BY THE TIME THEY GOT BACK OUT THERE IT WAS SOAKED IN AND DRIED UP AND NONE COULD BE RECOVERED WITHOUT DOING MORE DAMAGE THAN HARM. NOTHING COULD BE DONE FOR CLEANUP.

11/16 ERDMAN SPOKE WITH THE DAIRY. REPAIRS ARE BEING MADE TO THE TRUCK TO COVER THE SWITCH SO IT CANNOT BE ACCIDENTALLY HIT WHILE DRIVING.

WTM START: 697525, 391942

WTM END: 697260, 391935

Person Reporting

☐ Anonymous ☐ Violation ☒ RP Contact

STEVE OHLROGGE

MAPLE LEAF DAIRY

CROP MANAGER

(920) 374-1505

Documents and Images

pdf 20151115NE361_Map.pdf

20151115NE361_Map

Closure

Regional Spill Coordinator

Beth A Erdman (920) 303-5410

Docs Received On

11/16/2015

Date Closed

11/20/2015



MAPLE LEAF DAIRY



Legend

- Rivers and Streams
- Open Water
- Municipality
- State Boundaries
- County Boundaries
- Major Roads
 - Interstate Highway
 - State Highway
 - US Highway
- County and Local Roads
 - County HWY
 - Local Road
- Railroads
- Tribal Lands

0.1 0 0.04 0.1 Miles

NAD_1983_HARN_Wisconsin_TM

© Latitude Geographics Group Ltd.

1:2,498



DISCLAIMER: The information shown on these maps has been obtained from various sources, and are of varying age, reliability and resolution. These maps are not intended to be used for navigation, nor are these maps an authoritative source of information about legal land ownership or public access. No warranty, expressed or implied, is made regarding accuracy, applicability for a particular use, completeness, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: <http://dnr.wi.gov/org/legal/>

Note: Not all sites are mapped.

Notes

Spill Location: Red Dot/Line

WTM Start: 697524, 391942
WTM End: 967260, 391935